

RGT-1508

## Product Description

### Baby stroller walking bumpy tester

CE



#### Product description:

Stroller walking bumpy tester

is produced according to CNS baby strollers dynamic durability test specification. Methods of test: the model baby in the car, the car will be fixed on the test bench, the belt speed can be adjusted to  $1.4 \pm 0.1$  m/s ec (  $5 \text{ km/h} \pm 3.6 \text{ km/h}$  ). After 64 hours of continuous testing, visual platform if is damaged. After a set number of times can automatically stop operation.

This machine is equipped with electric eye safety device, can prevent the handle and rubber beam ring fracture causing stroller runaway to damage the test machine. This machine is suitable for durability test of hand pushing pram simulation traffic movement vehicle and bottom dynamic wheel.

#### Correspond Standard:

EN1888: 2003 Clause 17.2

## RGT-1508

	Baby stroller walking bumpy tester
Test work	1、 2 station (optional)
Test speed	5kw/h±0.1kw/h (adjustable)
Drive mode	The roller drive rubber conveyor belt and add drum reinforcement with special aluminum alloy belt actuator.
Drive horsepower	AC380V×3 diameter ×3HP
Adjust the distance	Max. 300mm
Effective width	Max. 1000mm
Test count	LCD, 0-999, 999
Bearing load	Max. 100Lb
Power	AC380V×3 diameter ×5KW
Size	(L×W×H) 3300×1400×1900mm
Weight	about 600kg
Impact block shape	Trapezoidal, half arc or designated

**Baby car as far as possible not to use in any of the following circumstances:**

- 1.Vibration, rocking occasions.
- 2.Direct sunlight.
- 3.Hot, dusty, humid places.
- 4.The AC power supply should be well grounded, to ensure safe use.
- 5.It is prohibited to use strong solvents, such as benzene, nitro categories oil for cleaning machine.
- 6.Shall not be injected into the water and debris inside the machine, in order to prevent damage to electrical components and electrical shock.
7. The disassembling and assembling and debugging of the instrument display can only be approved by the national metrology units and the company, other people are not allowed to overhaul.